

Date Issued	May 07, 2025	Status	Closed
Provider Name	SUPER TITANS		
Provider ID	018042859		
Provider Address	725 E Kevin Dr, Tea, SD 57064, USA		
Provider Contact	Kelly Irvin		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

During the inspection, it was observed that the exit light on the south door failed to illuminate.

The fire extinguishers were not serviced, and the ones observed were Kidde one-time disposable fire extinguishers.

Corrections to be Made:

Exit signs must be provided over each exit and, where necessary, to identify a change in the direction of egress travel.

They must be

interior, exterior, illuminated, or self-luminous.

The fire extinguishers must be

inspected and serviced annually by a qualified service technician.

Corrections Made:

The provider submitted verification to the Office of Licensing & Accreditation indicating that the exit light has been serviced by a qualified technician and is functioning properly. The fire extinguishers have been inspected and are

current.

Anticipated Completion Date:
June 06, 2025

Date Completed:
May 22, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Kelly Irvin
Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

May 07, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Teri Pieters
Printed Name of DSS Staff



Signature of DSS Staff:

May 23, 2025

Date