

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Montessori School of Aberdeen Inc.** City: **Aberdeen**

Provider Number: **011102504**

Inspector: **Clint Rux**

Date of Inspection: **06/23/2023**

Time of Inspection: **10:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## B. ENVIRONMENTAL HEALTH

22. Does the construction of walls, ceilings, doors, window and skylights appear clean and in good repair?  
Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:	Agency Action:	
<b>The wall in the women's bathroom on the lower level in the last stall has paint peeling and bubbled sheet rock.</b>	<b>Compliance Plan</b>	
<b>The bathroom wall needs to be in good repair.</b>	Suggested Completion Date:	Actual Completion Date:
<b>Correction: The wall in the women's lower-level bathroom was repaired and painted.</b>	<b>07/14/2023</b>	<b>07/31/2023</b>
	Status: <b>Corrected</b>	

**Susan Dalager**

Provider Signature

**06/23/2023**

Date

**Clint Rux**

Inspector Signature

**06/23/2023**

Date