COMPLIANCE PLAN
OFFICE OF LICENSING & ACCREDITATION

South Dakota Department of Social Services

Date Issued	October 19, 2026	Status	Closed

Provider Name	MITCHELL CHRISTIAN EARLY LEARNING
Provider ID	014511763
Provider Address	805 W 18th Ave, Mitchell, SD 57301, USA
Provider Contact	Sarah Lieber

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

(1) A working smoke detector must be located on each level of the home;
(2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
(3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
(4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
(5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At the time of the inspection, a light on the fire alarm system indicated that it was not functioning properly. A carbon monoxide detector was not observed during the inspection.

Corrections to be Made:

The fire alarm system is to maintained as functional. A carbon monoxide detector is to be installed.

Corrections Made:

Verification was received that both issues noted were corrected.

Anticipated Completion Date:
October 20, 2026

Date Completed:
October 29, 2026

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Sarah Joelle Lieber
Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

October 19, 2026
Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Deb Bigge
Printed Name of DSS Staff



10/14/2026, 10:39:25 AM
Signature of DSS Staff:

October 13, 2026
Date