

Date Issued May 13, 2025 Status Closed

Provider Name HAMLIN COMMUNITY DAYCARE

Provider ID 011515290

Provider Address 44575 188th St, Hayti, SD 57241, USA

Provider Contact Amy Fuller

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At time of inspection, items were being stored by the north exit that reduced egress to less than 36".

Corrections to be Made:

Exit width is to be maintained at 36 inches or more; exits can not be obstructed.

Corrections Made:

Verification received on 5/9/2025 that the north exit has been cleared and exit path is maintained at 36 inches or more.

Anticipated Completion Date:

May 13, 2025

Date Completed:

May 13, 2025

Compliance Plan Action #2

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child. For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

At time of inspection, outlets in restrooms were not tamper-resistant or self-closing. Outlet plug covers were being used.

Corrections to be Made:

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Corrections Made:

Verification received that outlet covers have been replaced with tamper-resistant covers.

Anticipated Completion Date:
May 09, 2025

Date Completed:
May 09, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Amy Fuller

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

May 13, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Ambuer Jaacks

Printed Name of DSS Staff



5/13/2025, 4:47:48 PM

Signature of DSS Staff:

May 13, 2025

Date