

Date Issued	June 16, 2025	Status	Closed
Provider Name	<u>TEA TRAILBLAZERS CHILD CARE CENTER</u>		
Provider ID	<u>018043072</u>		
Provider Address	<u>2100 Devon Ave, Tea, SD 57064, USA</u>		
Provider Contact	<u>Amanda And Joe McGregor</u>		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

The fire system maintenance report was unavailable during the inspection.

The exit signs and lighting could not be tested during the visit because the necessary components for functional testing were not operational.

Corrections to be Made:

The fire system must be inspected and serviced annually by a qualified service technician.

Exit signs must be provided over each exit and, where necessary, to identify a change in the direction of egress travel.

They must be interior, exterior, illuminated, or self-luminous.

Corrections Made:

The fire system was inspected by a qualified technician. The licensing specialist confirmed during a visit on 5/29/25 that all exit signs are illuminated.

The licensing specialist confirmed during a visit on 5/29/25 that all exit signs are illuminated.

Anticipated Completion Date:
June 16, 2025

Date Completed:
June 16, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Amanda McGregor (Provider signed compliance plan outside the system)
Printed Name of Provider/Agency Contact

Signature of Provider/Agency Contact

May 29, 2025
Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Teri Pieters
Printed Name of DSS Staff



6/6/2025, 3:26:22 PM

Signature of DSS Staff:

June 06, 2025
Date