

Date Issued	August 07, 2025	Status	Closed
Provider Name	DASH		
Provider ID	011517579		
Provider Address	695 Palisades Ave, Toronto, SD 57268, USA		
Provider Contact	Lindsay Rogness		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At time of inspection, paths of egress were not fully accessible due to school equipment restricting direct access to exits.

Fire extinguishers didn't appear to be visible and accessible due to equipment stored in path of access.

Corrections to be Made:

Exit paths must remain unobstructed, and fire extinguishers should be clearly visible and easily accessible.

Corrections Made:

Verification was received that items in the hallways have been removed to clear the area for an accessible exit. The wading pool was also removed from the area where the fire extinguisher is stored to ensure easy access.

Anticipated Completion Date:

August 12, 2025

Date Completed:

August 07, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Lindsay Rogness

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

August 07, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Ambuer Jaacks

Printed Name of DSS Staff



8/5/2025, 9:58:18 AM

Signature of DSS Staff:

August 05, 2025

Date