

Date Issued August 21, 2025 Status Closed

Provider Name Knapp and Play Learning Center

Provider ID 1592614676

Provider Address 401 US-12, Webster, SD 57274, USA

Provider Contact Haven Begalka

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

There was no exit sign on the west door going to the playground.

There was no A 2A rated fire extinguisher by the kitchen nor one on the west side of the building.

Exit doors didn't have the crash bars on the main exit doors on the south side of the building.

Corrections to be Made:

Install and exit sign on the west door going to the playground.

Provide a 2A rated fire extinguisher in the kitchen area and one on the west side of the building.

The exit doors on the south side of the building need crash bars on the main exit doors.

Corrections Made:

An exit sign has been installed above the west door going to the playground.

A 2A rated fired extinguisher was installed in the kitchen area and in the west side of the building.

Crash bars were added on the main exit doors and on the south exit door.

Anticipated Completion Date:
September 11, 2025

Date Completed:
September 05, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Rainy K Hanson

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

August 21, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Julie Hermansen

Printed Name of DSS Staff



8/21/2025, 2:29:52 PM

Signature of DSS Staff:

August 21, 2025

Date