

Date Issued	November 03, 2025	Status	Closed
Provider Name	SIOUX VALLEY BASE		
Provider ID	010501748		
Provider Address	200 Hansina Ave, Volga, SD 57071, USA		
Provider Contact	Crystal Niemann		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At time of inspection, a carbon monoxide detector couldn't be located.

In corridors that provide access to exits, combustible decorations were coving more than 10% of the wall area.

Corrections to be Made:

School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapter 61:15:07.

Corrections Made:

Verification received that building is now equipped with a carbon monoxide detector.

Verification provided to show that combustible decorations in hallway corridors have been reduced to 10% or less.

Anticipated Completion Date:

November 11, 2025

Date Completed:

October 23, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Mary EK Schneider

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

November 03, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Ambuer Jaacks

Printed Name of DSS Staff



10/22/2025, 5:08:43 PM

Signature of DSS Staff:

October 22, 2025

Date