

Date Issued	November 26, 2025	Status	Closed
Provider Name	<u>CAMPUS LEARNING CENTER FOR CHILDREN</u>		
Provider ID	<u>018026052</u>		
Provider Address	<u>909 W 33rd St, Sioux Falls, SD 57105, USA</u>		
Provider Contact	<u>Judy Knadel</u>		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

At the time of the inspection, the outlets in room 104 are not self closing or tamper resistant.

Corrections to be Made:

All outlets must be self closing, or tamper resistant. Documentation of correction to be provided to the Office of Licensing and Accreditation.

Corrections Made:

Self closing outlet covers have been installed as required. Photo documentation received on 11-25-2025.

Anticipated Completion Date:

November 30, 2025

Date Completed:

November 25, 2025

Compliance Plan Action #2

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At the time of the inspection, the fire extinguisher in the hall was last inspected in December 2023.

Corrections to be Made:

Fire extinguisher to be inspected annually. Documentation of inspection to be provided to the Office of Licensing and Accreditation.

Corrections Made:

Documentation of annual inspection received on 11-24-2025.

Anticipated Completion Date:
November 30, 2025

Date Completed:
November 24, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Judy Knadel

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

November 07, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Rita Trager

Printed Name of DSS Staff



11/7/2025, 8:03:02 AM

Signature of DSS Staff:

November 05, 2025

Date