
Date Issued	November 21, 2025	Status	Closed
Provider Name	<u>ST. PAUL'S LUTHERAN PRESCHOOL & DAY</u>		
Provider ID	<u>016598628</u>		
Provider Address	<u>835 E Fairmont Blvd, Rapid City, SD 57701, USA</u>		
Provider Contact	<u>Nicole Maddox</u>		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

The electrical outlets are not tamper-resistant or contain a self-closing cover.

Corrections to be Made:

Program will replace the electrical outlets with a self-closing outlet cover or tamper-resistant outlets and submit verification to the Office of Licensing & Accreditation.

Corrections Made:

Program replaced the electrical outlets with a tamper-resistant outlet and submitted verification to the Office of Licensing & Accreditation.

Anticipated Completion Date:

December 05, 2025

Date Completed:

November 28, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Nicole Maddox

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

November 21, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Andrea Neff

Printed Name of DSS Staff



11/14/2025, 12:03:22 PM

Signature of DSS Staff:

November 14, 2025

Date