

Date Issued	December 15, 2025	Status	Closed
Provider Name	<u>Savannah Burton</u>		
Provider ID	<u>1173058237</u>		
Provider Address	<u>926 Ziebach St, Rapid City, SD 57703, USA</u>		
Provider Contact	<u>Savannah Burton</u>		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

The provider did not have a 2A rated fire extinguisher.
The provider did not have a carbon monoxide detector.

Corrections to be Made:

A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area. Verification that this has been installed must be submitted to the Office of Licensing and Accreditation.

A carbon monoxide detector must be installed, according to the manufacturer's instructions. Verification that this has been installed must be submitted to the Office of Licensing and Accreditation.

Corrections Made:

Provider sent in verification that she had purchased a 2A rated fire extinguisher and a carbon monoxide detector.


Anticipated Completion Date:
December 26, 2025

Date Completed:
December 29, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Savannah Burton

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

December 15, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Tina Uecker

Printed Name of DSS Staff



Signature of DSS Staff:

December 15, 2025

Date