

|                  |                                          |        |        |
|------------------|------------------------------------------|--------|--------|
| Date Issued      | January 26, 2026                         | Status | Closed |
| Provider Name    | SKIES THE LIMIT ACADEMY                  |        |        |
| Provider ID      | 016597854                                |        |        |
| Provider Address | 85 Custer Ave, FORT MEADE, SD 57741, USA |        |        |
| Provider Contact | Ariel Lewis                              |        |        |

**The items listed below are those that the provider was not in compliance with at the time of the inspection.**

### **Compliance Plan Action #1**

**Administrative Rule:**

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

**Summary of Non-Compliance Finding:**

Program has paper posted on emergency exit doors in toddler/infant building. Preschool room has dangling decoration at transition between entry and classroom area.

**Corrections to be Made:**

Program will need to remove the paper and decorations from all emergency exit doors.

**Corrections Made:**

Program removed the paper and decorations from all emergency exit doors.

**Anticipated Completion Date:**  
June 17, 2025

**Date Completed:**  
June 12, 2025

## Compliance Plan Action #2

### **Administrative Rule:**

67:42:17:32

All walls, ceilings, floors, and equipment must be easily cleanable, kept clean, and in good repair. Heating and cooling systems must maintain a temperature between sixty-five degrees Fahrenheit and seventy-five degrees Fahrenheit. For a child care center and school-age program, all heating and cooling systems must be inspected annually, by a certified technician.

Food preparation areas, including tables and countertops, must be made of a smooth, nonporous material, kept clean and sanitized, be free of cracks, and be in good repair. Center and school-age programs, in which more than twenty children are cared for, must provide a ventilation hood over all cooking areas. The hood must be appropriate for the type of appliance and intended use, as required in § 61:15:01:01.

### **Summary of Non-Compliance Finding:**

Program is using duct tape to protect sharp edges on heat register in infant building.

There is a gap/sharp edge on heat register in preschool room.

The exterior stairs leading to the preschool room are damaged.

### **Corrections to be Made:**

Program will need to repair the sharp edges and gap on the heat register in the infant building and preschool room.

Program will need to repair the exterior stairs leading to the preschool room.

### **Corrections Made:**

Program repaired the exterior stairs leading to the preschool room.

Program ordered new heat covers for the heat register in the infant building and preschool room; heat covers are on back order. In the meantime, the program has covered the sharp edges and heat register with a foam heating strip.

Verification that the heat register covers were replaced was received on 8/25/25.

**Anticipated Completion Date:**  
January 26, 2026

**Date Completed:**  
August 25, 2025

**Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.**

Ariel Britton

Printed Name of Provider/Agency Contact



\_\_\_\_\_  
Signature of Provider/Agency Contact

\_\_\_\_\_  
June 05, 2025

\_\_\_\_\_  
Date

\_\_\_\_\_  
**The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.**

\_\_\_\_\_  
Andrea Neff

\_\_\_\_\_  
Printed Name of DSS Staff



6/3/2025, 2:44:19 PM

\_\_\_\_\_  
Signature of DSS Staff:

\_\_\_\_\_  
June 03, 2025

\_\_\_\_\_  
Date