

Date Issued May 06, 2026 Status Closed

Provider Name TIGER TOTS PRESCHOOL AND CHILDCARE

Provider ID 018042435

Provider Address 100 South Shebal Ave, Harrisburg, SD 57032, USA

Provider Contact Samantha Weber

**The items listed below are those that the provider was not in compliance with at the time of the inspection.**

### Compliance Plan Action #1

#### **Administrative Rule:**

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

#### **Summary of Non-Compliance Finding:**

Emergency lighting did not function when tested in the preschool room.

The emergency exit in the preschool room was blocked.

At the time of inspection, there was no carbon monoxide detector at the time of the inspection.

#### **Corrections to be Made:**

The program will provide the Office of Licensing and Accreditation with documentation and photographs verifying that carbon monoxide detectors has been installed. The program will provide the Office of Licensing and Accreditation with documentation demonstrating that the preschool exit has been cleared to a minimum width of 36 inches. The program

will provide the Office of Licensing and Accreditation with documentation and photographs verifying that the emergency lighting in the preschool room is functioning properly.

**Corrections Made:**

The program provided the Office of Licensing and Accreditation with documentation and photographs verifying that carbon monoxide detectors have been installed.

The program provided the Office of Licensing and Accreditation with documentation demonstrating that the preschool exit has been cleared to a minimum width of 36 inches.

The program provided the Office of Licensing and Accreditation with documentation and photographs verifying that the emergency lighting in the preschool room is functioning properly.

**Anticipated Completion Date:**

May 29, 2026

**Date Completed:**

June 04, 2026

**Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.**

Samantha Weber

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact


May 06, 2026

Date

**The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.**

Teri Pieters

Printed Name of DSS Staff



4/29/2026, 10:25:06 AM

Signature of DSS Staff:

April 29, 2026

Date