

Date Issued	June 10, 2026	Status	Closed
Provider Name	VIBRANT MINDS LEARNING CENTER		
Provider ID	018043222		
Provider Address	4101 W Valhalla Blvd, Sioux Falls, SD 57106, USA		
Provider Contact	Ashley Grey		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

The brown outlet in the Transition Room and the white outlet in the Cuddler's Room are not tamper-resistant or self-closing.

Corrections to be Made:

The program will replace the two outlets with tamper-resistant or self-closing outlets and submit verification of completion to the Office of Licensing and Accreditation.

Corrections Made:

The program replaced the two outlets with tamper-resistant outlets and submitted verification to the Office of Licensing and Accreditation.

Anticipated Completion Date:
July 03, 2026

Date Completed:
June 23, 2026

Compliance Plan Action #2

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

Storage room items were being stored too close to the ceiling and the sprinkler head.

Corrections to be Made:

The facility will clean and organize the storage room to maintain proper clearance around the sprinkler heads. Photos of the completed corrections will be submitted to the Office of Licensing and Accreditation.

Corrections Made:

The program provided photos of the organized storage room and proper clearance to the Office of Licensing and Accreditation.

Anticipated Completion Date:

July 03, 2026


Date Completed:

June 23, 2026

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Lacey Tebay

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

June 10, 2026


Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above

plan.

Teri Pieters

Printed Name of DSS Staff

A handwritten signature in black ink that reads "Teri Pieters". The signature is written in a cursive style with a large, looped "P".

6/8/2026, 8:39:59 AM

Signature of DSS Staff:

June 08, 2026

Date
