

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Ipswich Tiger Post Community Education Center**

City: **Ipswich**

Provider Number: **011100998**

Inspector: **Clint Rux**

Date of Inspection: **05/17/2022**

Time of Inspection: **12:15 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:	Agency Action:	
Combustible material was stored within 2 feet of the ceiling in the back corner of the storage room.	Compliance Plan	
Combustible materials need to be maintained at least 2 feet below the ceiling or 18 inches below sprinkler head deflectors.	Suggested Completion Date:	Actual Completion Date:
Correction: The combustible materials were moved to meet the storage room requirements.	05/27/2022	05/25/2022
	Status: Corrected	

Jada Saucedo

Provider Signature

05/17/2022

Date

Clint Rux

Inspector Signature

05/17/2022

Date