

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Sisseton/Wahpeton Head Start Center West**

City: **Agency Village**

Provider Number: **017508141**

Inspector: **Eric Anderson**

Date of Inspection: **03/20/2023**

Time of Inspection: **9:47 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

14. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

Corrections To Be Made:	Agency Action:	
<b>Items on the top shelf in the storage room on the NW side of the building are too close to the ceiling.</b>	<b>Compliance Plan</b>	
<b>In storage rooms, combustible material must be at least 2 feet below the ceiling or 18 inches below sprinkler head deflectors.</b>	Suggested Completion Date:	Actual Completion Date:
<b>Correction: The items in the storage room on the NW side of the building were maintained at least 2 feet below the ceiling.</b>	<b>04/10/2023</b>	<b>03/20/2023</b>
	Status: <b>Corrected</b>	

**Fred Arcoren**

Provider Signature

**03/20/2023**

Date

**Eric Anderson**

Inspector Signature

**03/20/2023**

Date