

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **School of Early Education - Sioux Falls**

City: **Sioux Falls**

Provider Number: **018042607**

Inspector: **Todd Lowe**

Date of Inspection: **02/22/2024**

Time of Inspection: **9:51 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

An exit door and pathway were obstructed.

All exits are to be maintained in a safe manner and unobstructed.

Correction: All exits were cleared of obstruction.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/22/2024

Actual
Completion
Date:

02/22/2024

Status: **Corrected Immediately**

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

Corrections To Be Made:

Storage in the utility closet on the main floor was less than 24 inches from the ceiling. The height of the storage displaced the heat detector head to be unsecured in the mounting bracket.

In storage rooms, combustible materials need to be maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors.

Correction: Combustible materials were moved and are maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors. The heat detector head was secured in the mounting bracket.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

02/22/2024

Actual
Completion
Date:

02/22/2024

Status: **Corrected Immediately**

Chelsea DeJonge

Provider Signature

02/22/2024

Date

Todd Lowe

Inspector Signature

02/22/2024

Date