

Compliance Monitoring Report Compliance Plan

Provider's Name: **Amber Long**

City: **Sioux Falls**

Provider Number: **018043006**

Inspector: **Stacie Ugofsky**

Date of Visit/Report: **09/13/2022**

Time of Visit/Report: **8:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Miscellaneous Rule Violations

67:42:03:11.03 - Emergency preparedness and response.

Issue/Corrections To Be Made:	Agency Action:	
There is more than 44 inches between the bottom of the egress window and the floor in the basement.	Compliance Plan	
A stable and permanent platform must be used that raises the level of the floor such that the distance is 44 inches or less between the bottom of the window and the platform landing.	Suggested Completion Date:	Actual Completion Date:
Correction: A stable and permanent platform was added so there is 44 inches or less between the bottom of the window and the platform landing.	10/01/2022	10/13/2022
	Status: Corrected	

Provider Signature

Date

Stacie Ugofsky

Inspector Signature

Date