

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **GARFIELD ELEMENTARY CLC** City: **Sioux Falls**

Provider Number: **018043147**

Inspector: **Todd Lowe**

Date of Inspection: **08/22/2023**

Time of Inspection: **1:26 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

Corrections To Be Made:

During the inspection, there were items being stored in the metal bar joists of the ceiling in room 158 and it is blocking the sprinkler heads.

Combustible materials must be maintained at lease 18 inches below sprinkler head deflectors.

***Correction: Items have been removed.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/30/2023

Actual
Completion
Date:

10/13/2023

Status: **Corrected**

Saundra Larson

Provider Signature

08/22/2023

Date

Todd Lowe

Inspector Signature

08/22/2023

Date