

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **SFSD Jr. Kindergarten EC at JFK**

City: **Sioux Falls**

Provider Number: **018043194**

Inspector: **Sarah Boese**

Date of Inspection: **10/17/2024**

Time of Inspection: **9:10 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

19. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 61:15:01:01

Corrections To Be Made:

Storage bins located in Jr. Kindergarten Room for extended care plus are within 2 feet from ceiling.

Combustible materials are to be maintained at least 2 feet below the ceiling or 18 inches below sprinkler head deflectors.

***Correction: bins have been moved to two feet below ceiling.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

10/27/2024

Actual
Completion
Date:

10/22/2024

Status: **Corrected**

Mary K. Schuerman

Provider Signature

10/17/2024

Date

Sarah Boese

Inspector Signature

10/17/2024

Date