

Date Issued	July 07, 2025	Status	Closed
Provider Name	CHILDREN'S CARE CORNER CAMP INSPIRATION		
Provider ID	014512605		
Provider Address	500 N Co Hwy 42, Howard, SD 57349, USA		
Provider Contact	Abby Anderberg-Kramer		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

Self closing outlet covers or tamper resistant outlets are needed on the south wall.

Corrections to be Made:

Compliant outlet covers must be installed with an expected completion date of 06/25/25.

Corrections Made:

Verification was received on 07/11/25 that the issue was corrected.

Anticipated Completion Date:
July 07, 2025

Date Completed:
July 11, 2025

Compliance Plan Action #2

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

Combustible materials were stored within 24 inches of the ceiling in the kitchen area.

Corrections to be Made:

Combustible items must be moved to a location at least 24 inches from the ceiling by 06/25/25.

Corrections Made:

Verification was received that the items were moved.

Anticipated Completion Date:

July 07, 2025

Date Completed:

July 14, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Abby Anderberg-Kramer

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

July 07, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Deb Bigge

Printed Name of DSS Staff



6/18/2025, 3:28:34 PM

Signature of DSS Staff:

June 18, 2025

Date
