

Date Issued	July 14, 2025	Status	Closed
Provider Name	SCARBROUGH CENTER		
Provider ID	018030125		
Provider Address	2304 N Lackey Pl, Sioux Falls, SD 57107, USA		
Provider Contact	Robin Sjogren		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

At the time of the inspection, the fire alarm system was in trouble mode indicating that the smoke detector was not operating. Additionally, the exterior exit door in the infant room had a partial obstruction.

Corrections to be Made:

Child care centers shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05. This includes keeping exit door pathways clear and having an operational fire alarm system.

Corrections Made:

The partial obstruction in front of the exterior exit door in the infant room was immediately removed. The head was

replaced and the fire alarm system is operational.

Anticipated Completion Date:
September 01, 2025

Date Completed:
July 28, 2025

Compliance Plan Action #2

Administrative Rule:

67:42:17:26

A nap mat, blanket, or other sleep surface, other than the floor, for children over one year of age must be available for each child during nap time.

A sleep surface must be maintained in good repair.

A provider shall follow the safe sleep practices contained in **Caring for Our Children: National Health and Safety Performance Standards, 4th Edition**, for infants under the age of one.

Summary of Non-Compliance Finding:

Nap mats had torn seams, exposing the foam inside.

Corrections to be Made:

A sleep surface must be maintained in good repair.

Corrections Made:

Nap mats were replaced and will be kept in good repair.

Anticipated Completion Date:
July 18, 2025

Date Completed:
July 14, 2025

Compliance Plan Action #3

Administrative Rule:

67:42:17:44

All toxic or hazardous substances must be:

- (1) Inaccessible to children;
- (2) Used according to manufacturer's instructions;
- (3) Stored in the original or other labeled container; and
- (4) Disposed of according to manufacturer recommendations.

Bio-contaminants must be handled and disposed of properly.

Soiled diapers must be changed promptly, in a designated area, on a non-porous surface. The diaper changing area must be clean and disinfected with a sanitizing solution approved by the department. Soiled diapers must be kept in a leakproof, nonabsorbent container that is covered with a tight-fitting lid.

Summary of Non-Compliance Finding:

The diaper changing table was dirty at the time of the inspection.

Corrections to be Made:

The diaper changing area must be clean and disinfected with a sanitizing solution approved by the department.

Corrections Made:

The diaper changing table was cleaned and cleaning practices were reviewed with all providers.

Anticipated Completion Date:

July 14, 2025

Date Completed:

July 14, 2025

Compliance Plan Action #4**Administrative Rule:**

67:42:17:35

Playgrounds for all child care settings must be safe, in good repair, and free of debris, trash, and weeds. Playground equipment must be installed according to the manufacturer's instructions and maintained in good repair.

For a center program, a fence that measures at least four feet high is required around the center's outdoor play space.

For a family day care or school-age program, a fence that measures at least forty-two inches high may be required to separate the outdoor play space, if the department determines a body of water, vehicular traffic, or other hazard poses a risk of injury or death to a child.

Summary of Non-Compliance Finding:

A thistle was observed in the outside play area that causes a potential hazard.

Corrections to be Made:

Playgrounds for all child care settings must be safe, in good repair, and free of debris, trash, and weeds.

Corrections Made:

The thistle was removed from the outside play area.

Anticipated Completion Date:

July 18, 2025


Date Completed:

July 14, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Robin Sjogren

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

July 14, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Brooke Flemmer

Printed Name of DSS Staff



7/10/2025, 3:16:41 PM

Signature of DSS Staff:

July 10, 2025

Date