COMPLIANCE PLAN OFFICE OF LICENSING & ACCREDITATION



Date Issued May 05, 2025 Status Closed

Provider Name SUNNYSIDE DAYCARE

Provider ID 011517588

Provider Address 1408 N Harrison Ave, Pierre, SD 57501, USA

Provider Contact Katie Big Eagle

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

There is a leak in their sprinkler system line, which needs to be repaired.

Corrections to be Made:

The program has requested additional time to repair the sprinkler system in order to secure a service technician. Despite the leak, it has been confirmed that the sprinkler system is operational if needed in an emergency. The sprinkler line will be repaired by 7/31/2025.

Corrections Made:

The provider closed the program operation prior to correction.

August 01, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Daphne Thompson	
Printed Name of Provider/Agency Contact	
1) [
	May 05, 2025
Signature of Provider/Agency Contact	Date
The Department of Social Services, Office of Licensing and Ac	creditation has reviewed and accepted the above
plan.	
Sarah Deakins	
Printed Name of DSS Staff	
Fillited Name of DSS Staff	
425/0025, 2:55:36 PM	April 25, 2025
Signature of DSS Staff:	Date