

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Busy B's 2**

City: **Chamberlain**

Provider Number: **014512628**

Inspector: **Russ Lauritsen**

Date of Inspection: **08/29/2024**

Time of Inspection: **10:02 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Miscellaneous Rule Violations

61:15:05:15 - Basement requirements.

Corrections To Be Made:	Agency Action:	
There are several breaches in the basement ceiling sheetrock protecting the floor joists.	Compliance Plan	
If the construction of the floor joists separating the basement from the first story consists of metal or wood, the framing shall be enclosed on the basement side.	Suggested Completion Date:	Actual Completion Date:
The program has sent verification that the breaches in the basement ceiling sheetrock has been repaired.	10/25/2024	10/11/2024
	Status: Corrected	

Blakely Nagy

Provider Signature

08/29/2024

Date

Russ Lauritsen

Inspector Signature

08/29/2024

Date