

Date Issued	April 02, 2025	Status	Closed
Provider Name	WANBLI CINCALA TAWAHOHPE LITTLE EAGLES NEST		
Provider ID	016597799		
Provider Address	206 School St, Batesland, SD 57716, USA		
Provider Contact	Sarah Clifford		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

Fire extinguishers were last inspected in May 2023.

During the inspection it could not be determined if the building had propane, which requires carbon monoxide detectors to be installed.

Corrections to be Made:

Program will ensure the fire extinguishers are inspected by a certified technician and submit the verification to the Office of Licensing & Accreditation.

Program will either install a carbon monoxide detector according to the manufacturer's instructions or submit proof that the building does not have fuel burning appliances.

Corrections Made:

Fire extinguishers were inspected by a certified technician.

Program verified that carbon monoxide detectors are installed in both classrooms.

Anticipated Completion Date:

April 11, 2025

Date Completed:

June 16, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Sarah Clifford

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

April 02, 2025

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Andrea Neff

Printed Name of DSS Staff



3/31/2025, 10:50:24 AM

Signature of DSS Staff:

March 31, 2025

Date