

Date Issued	October 08, 2025	Status	Closed
Provider Name	Boys & Girls Club of the Capital Area		
Provider ID	014512557		
Provider Address	110 S Ree St, Pierre, SD 57501, USA		
Provider Contact	Samson Boutchee		

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

An outlet in the library does not have a self-closing or tamper resistant outlet cover.

Corrections to be Made:

A self-closing or tamper resistant outlet cover must be installed.

Corrections Made:

Verification of correction has been received.

Anticipated Completion Date:
October 08, 2025

Date Completed:
October 08, 2025

Compliance Plan Action #2

Administrative Rule:

67:42:17:32

All walls, ceilings, floors, and equipment must be easily cleanable, kept clean, and in good repair. Heating and cooling systems must maintain a temperature between sixty-five degrees Fahrenheit and seventy-five degrees Fahrenheit. For a child care center and school-age program, all heating and cooling systems must be inspected annually, by a certified technician.

Food preparation areas, including tables and countertops, must be made of a smooth, nonporous material, kept clean and sanitized, be free of cracks, and be in good repair. Center and school-age programs, in which more than twenty children are cared for, must provide a ventilation hood over all cooking areas. The hood must be appropriate for the

type of appliance and intended use, as required in § 61:15:01:01.

Summary of Non-Compliance Finding:

The air vent in room 207 is broken and has sharp metal edges.

Corrections to be Made:

The air vent grate must be replaced. The program has asked for additional time to replace this vent grate as it needs to be ordered, welded, and painted. They expect to have this completed no later than November 28, 2025. In the meantime, the area where the vent is located is blocked off from children.

Corrections Made:

Verification has been received.

Anticipated Completion Date:
November 28, 2025

Date Completed:
December 03, 2025

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Samson Boutchee
Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

October 01, 2025
Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Sarah Deakins
Printed Name of DSS Staff



Signature of DSS Staff:

September 26, 2025
Date