

Date Issued March 25, 2026 Status Closed

Provider Name ST. PETER'S CHILD CARE
Provider ID 019519800
Provider Address 318 Main St, Jefferson, SD 57038, USA
Provider Contact Erin Hammitt

The items listed below are those that the provider was not in compliance with at the time of the inspection.

Compliance Plan Action #1

Administrative Rule:

67:42:17:39

For family day care providers, unused electrical outlets must have an outlet plug cover, have a tamper-resistant cover, or be made inaccessible to a child.

For center and school-age programs, unused electrical outlets must have a self-closing outlet cover or tamper-resistant cover.

Summary of Non-Compliance Finding:

Electrical outlets in the Parish Hall, which is a newly planned area for use, do not have self-closing or tamper resistant childproof electrical covers. Some outlets had plugs, which are not permitted.

Corrections to be Made:

These outlets need to be replaced with outlets that are self-closing or tamper resistant.

Corrections Made:

Electrical outlets in the Parish Hall, were replaces to be tamper resistant.

Anticipated Completion Date:
April 10, 2026

Date Completed:
May 13, 2026

Compliance Plan Action #2

Administrative Rule:

67:42:17:37

Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:05 and 61:15:06. School-age programs operating in a school building shall follow applicable construction and fire safety requirements, as outlined in chapters 61:15:01, 61:15:02, and 61:15:07.

A family day care home must have the following fire safety measures in place:

- (1) A working smoke detector must be located on each level of the home;
- (2) A fully charged, portable fire extinguisher, with a minimum 2A rating, as identified on the extinguisher label, must be kept in or within fifteen feet of the kitchen or food preparation area;
- (3) A carbon monoxide detector must be installed, according to the manufacturer's instructions, if a fuel burning appliance is present in the home;
- (4) Each level of the home must have at least two remote exits that shall remain clear of obstructions. One of these exits must be a standard-sized door, and the other may be either a standard-sized door or an unobstructed, operable window, having at least five square feet of openable space, with a minimum width of twenty inches and a minimum height of twenty-four inches; and
- (5) Whenever a portable space heater, a wood burning stove, or a fireplace is in use, the heater, stove, or fireplace must be inaccessible to children.

Summary of Non-Compliance Finding:

A carbon monoxide detector was not located in Parish Hall.

Corrections to be Made:

Since the new area used for child care is in a separate building than the rest of the day care, a carbon monoxide detector should be in both locations.

Corrections Made:

A carbon monoxide detector was installed in the Parish Hall.

Anticipated Completion Date:

April 10, 2026

Date Completed:

May 13, 2026

Compliance Plan Action #3

Administrative Rule:

67:42:17:02

Before submitting to the department an application for licensure, a center or school-age program shall submit to the department a copy of a building, renovation, or alteration plan, and obtain the department's approval of the plan.

The department shall, within sixty days after receiving a completed application, provide to the applicant written notice of the department's approval or denial of licensure or registration. If the department denies the licensure or registration, the department shall provide the reason for the denial.

An applicant may reapply after taking corrective action related to each reason listed in the denial.

Summary of Non-Compliance Finding:

An outlet between the sinks in the women's

restroom in the Parish Hall was not provided with a GFCI.

Corrections to be Made:

All requirements identified in the floor plan review letters issued by the Fire Marshall's Office and the Dept. of Health need to be addressed. Any electrical outlet within 6 feet of any water source is required to be Ground Fault Circuit Interrupter (GFCI) protected.

Corrections Made:

The outlet between the sinks in the women's restroom is connected to a GFCI breaker.

Anticipated Completion Date:

April 10, 2026


Date Completed:

May 13, 2026

Your signature below certifies you have read and understand the non-compliance findings and agree to make corrections to be compliant with the identified administrative rules.

Erin Hammitt

Printed Name of Provider/Agency Contact



Signature of Provider/Agency Contact

March 18, 2026

Date

The Department of Social Services, Office of Licensing and Accreditation has reviewed and accepted the above plan.

Brooke Flemmer

Printed Name of DSS Staff



Signature of DSS Staff:

March 17, 2026

Date

3/17/2026, 2:55:29 PM