

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Hand In Hand Community Daycare**

City: **Miller**

Provider Number: **000097047**

Inspector: **Neal Cruse**

Date of Inspection: **09/24/2024**

Time of Inspection: **10:36 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

<p>Corrections To Be Made:</p> <p>There was no carbon monoxide detector on site.</p> <p>A carbon monoxide detector must be installed according to the manufacturer if there is a furnace or appliances utilizing fossil fuels.</p> <p>Verification that the program has installed two carbon monoxide detectors in their building was received.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">09/30/2024</td> <td style="text-align: center;">10/21/2024</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	09/30/2024	10/21/2024
Suggested Completion Date:	Actual Completion Date:				
09/30/2024	10/21/2024				

Nicole Werdel

09/24/2024

Provider Signature

Date

Neal Cruse

09/24/2024

Inspector Signature

Date