

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Bethesda Learning Academy**

City: **Aberdeen**

Provider Number: **000097106**

Inspector: **Clint Rux**

Date of Inspection: **06/21/2023**

Time of Inspection: **10:35 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

10. If providing care for children under 5 years of age, are there self-closing, or tamper resistant childproof electrical covers on all outlets? 67:42:11:10

|   |  |                            |                         |                   |                   |
|---|--|----------------------------|-------------------------|-------------------|-------------------|
| <p>Corrections To Be Made:</p> <p><b>The outlets in the infant room above the cribs and counter, an outlet by the door of the southeast room, and in the hall by the storage room were not self-closing. These outlets had outlet plug inserts.</b></p> <p><b>The electrical outlets need to be self-closing or tamper resistant.</b></p> <p><b>Correction: Self-closing outlets were installed in the locations noted.</b></p> | <p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>07/07/2023</b></td> <td style="text-align: center;"><b>07/31/2023</b></td> </tr> </table> <p>Status: <b>Corrected</b></p> | Suggested Completion Date: | Actual Completion Date: | <b>07/07/2023</b> | <b>07/31/2023</b> |
| Suggested Completion Date:  | Actual Completion Date:  |                            |                         |                   |                   |
| <b>07/07/2023</b>   | <b>07/31/2023</b>  |                            |                         |                   |                   |

## B. ENVIRONMENTAL HEALTH

67. Are swimming pools, that are not emptied after each use, fenced on all 4 sides? 67:42:11:02 NOTE: A wall of the facility is not considered a side of the fence, if the wall has a door access to the pool.

|   |  |                            |                         |                   |                   |
|---|--|----------------------------|-------------------------|-------------------|-------------------|
| <p>Corrections To Be Made:</p> <p><b>A pool that is not emptied after each use was being used in the courtyard off the dining room. This pool did not have a fence around it, and just a soft cover over it.</b></p> <p><b>Swimming pools not emptied after each use need to be fenced on all 4 sides with a 5ft fence and self-closing latched gate.</b></p> <p><b>Correction: The pool was drained and removed from the daycare property.</b></p> | <p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>07/01/2023</b></td> <td style="text-align: center;"><b>06/23/2023</b></td> </tr> </table> <p>Status: <b>Corrected</b></p> | Suggested Completion Date: | Actual Completion Date: | <b>07/01/2023</b> | <b>06/23/2023</b> |
| Suggested Completion Date:  | Actual Completion Date:  |                            |                         |                   |                   |
| <b>07/01/2023</b>   | <b>06/23/2023</b>  |                            |                         |                   |                   |

**Robin Loeb**

Provider Signature

**06/21/2023**

Date

**Clint Rux**

Inspector Signature

**06/21/2023**

Date