

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **USD Vucurevich Children's Center**

City: **Vermillion**

Provider Number: **000097127**

Inspector: **Stacy Wildermuth**

Date of Inspection: **05/07/2024**

Time of Inspection: **10:00 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

There is no carbon monoxide detector installed at the facility. The facility has a natural gas furnace.

A carbon monoxide detector must be installed according to the manufacturer's directions.

***Correction: Carbon monoxide detectors have been installed at the facility.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

05/14/2024

Status: **Corrected**

Actual
Completion
Date:

05/22/2024

B. Environmental Health

57. Is the outside play area safe, in good repair, and free of debris, trash, weeds and hazardous material? 67:42:17:35

Corrections To Be Made:

A large tree branch was downed by storm near playground equipment on the far east side of outside play area.

Outside play area must be free of debris.

***Correction: the tree branch has been removed.**

Agency Action:

Compliance Plan

Suggested
Completion
Date:

05/14/2024

Status: **Corrected**

Actual
Completion
Date:

05/08/2024

Dawna Andersen

Provider Signature

05/07/2024

Date

Stacy Wildermuth

Inspector Signature

05/07/2024

Date