

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Peace Lutheran Early
Childhood Center**

City: **Brookings**

Provider Number: **010604129**

Inspector: **Charles Schmidt**

Date of Inspection: **05/18/2023**

Time of Inspection: **1:34 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

15. Is electrical system being used properly? 61:15:01 NOTE: Check for overloads or frayed extension cords.

<p>Corrections To Be Made:</p> <p>The power strip in the toddler room was overloaded at the time of the inspection.</p> <p>The electrical system must be used properly.</p> <p>Correction: Verification received that power strip has been removed to ensure proper use.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">05/18/2023</td> <td style="text-align: center;">05/18/2023</td> </tr> </table> <p>Status: Corrected Immediately</p>	Suggested Completion Date:	Actual Completion Date:	05/18/2023	05/18/2023
Suggested Completion Date:	Actual Completion Date:				
05/18/2023	05/18/2023				

Stacy Sahr

Provider Signature

05/18/2023

Date

Charles Schmidt

Inspector Signature

05/18/2023

Date