

Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: **Kids Konnection**

City: **Beresford**

Provider Number: **010604233**

Inspector: **Michael Czmowski**

Date of Inspection: **11/07/2022**

Time of Inspection: **4:26 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

5. Are exits and exit corridors maintained in a safe manner; corridor widths must be maintained; exits are not be obstructed in any manner? 61:15:05:05

<p>Corrections To Be Made:</p> <p>NE Gym exit is blocked with rolling garbage cans.</p> <p>Ensure that all marked building exits are maintained and not blocked in any way.</p> <p>Correction: Removed the rolling garbage cans that were blocking the gym exit.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table border="0"> <tr> <td style="padding-right: 20px;">Suggested Completion Date:</td> <td>Actual Completion Date:</td> </tr> <tr> <td style="padding-right: 20px;">12/07/2022</td> <td>12/07/2022</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	12/07/2022	12/07/2022
Suggested Completion Date:	Actual Completion Date:				
12/07/2022	12/07/2022				

B. ENVIRONMENTAL HEALTH

17. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:

Heating/Cooling inspection report not available at time of inspection.

The heating and cooling systems need to be inspected annually.

Correction: The heating/cooling report is now posted in the area and was provided to licensing.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/07/2022

Actual
Completion
Date:

11/18/2022

Status: **Corrected**

Kaitlan Huggenberger

Provider Signature

11/07/2022

Date

Michael Czmowski

Inspector Signature

11/07/2022

Date