

**Facility Safety Inspection
Fire & Life Safety / Environmental Health
Before & After School Center - School Location
Compliance Plan**

Provider's Name: **B&G Club Robert Bennis ASE** City: **Brandon**

Provider Number: **010606118**

Inspector: **Patrick Waltman** Date of Inspection: **03/30/2023**

Time of Inspection: **3:28 PM**

Provider was found to be in full compliance

Kyle Hoffman

Provider Signature

03/30/2023

Date

Patrick Waltman

Inspector Signature

03/30/2023

Date