

Facility Safety Inspection

Fire & Life Safety / Environmental Health

Licensed Day Care Programs

Compliance Plan

Provider's Name: **Allen Learning Center**

City: **Allen**

Provider Number: **010606888**

Inspector: **Meredith Schrier**

Date of Inspection: **07/14/2022**

Time of Inspection: **10:37 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

16. Does the construction of walls, ceilings, doors, windows and skylights appear clean and in good repair? Are floor coverings clean and in good repair? Does outside appearance and construction appear in good repair? 67:42:11:39

Corrections To Be Made:

The front of the building is damaged and screens are ripped from hail damage and needs repair.

The construction of outside of the building need to be in good repair.

Correction: The damaged screens and siding have been replaced

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/30/2022

Actual
Completion
Date:

09/06/2022

Status: **Corrected**

43. Is the heating and cooling system maintained and inspected annually? 67:42:11:12

Corrections To Be Made:

The heating and cooling system hasn't had the annual inspection.

The heating and cooling system needs to be inspection annually.

Correction: The heating and cooling system was inspected on September 14, 2022

Agency Action:

Compliance Plan

Suggested
Completion
Date:

07/30/2022

Actual
Completion
Date:

09/16/2022

Status: **Corrected**

Vickie Dubray

Provider Signature

07/14/2022

Date

Meredith Schrier

Inspector Signature

07/14/2022

Date