

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **YMCA Youth Development Center**

City: **Aberdeen**

Provider Number: **011008567**

Inspector: **Clint Rux**

Date of Inspection: **08/28/2023**

Time of Inspection: **10:45 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

49. Are all walls, ceilings, floors, and equipment easily cleanable, kept clean and in good repair?
67:42:17:32

<p>Corrections To Be Made:</p> <p>There were holes in the north walls of the Lollipop and Storm classrooms; the walls also need painting.</p> <p>The holes in the north walls of the Lollipop and Storm classrooms need to be repaired and painted.</p> <p>Correction: The holes in the north walls of the Lollipop and Storm classrooms were repaired and painted.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">09/13/2023</td> <td style="text-align: center;">09/20/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	09/13/2023	09/20/2023
Suggested Completion Date:	Actual Completion Date:				
09/13/2023	09/20/2023				

Kaitlyn Fair

Provider Signature

08/28/2023

Date

Clint Rux

Inspector Signature

08/28/2023

Date