

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Ipswich Tiger Post Community Education Center**

City: **Ipswich**

Provider Number: **011100998**

Inspector: **Clint Rux**

Date of Inspection: **05/30/2024**

Time of Inspection: **11:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:	Agency Action:	
A carbon monoxide detector was not present in the facility.	Compliance Plan	
A carbon monoxide detector must be installed according to the directions.	Suggested Completion Date:	Actual Completion Date:
Correction: A carbon monoxide detector was installed according to the manufacturer's directions..	06/15/2024	06/11/2024
	Status: Corrected	

Jada Saucedo

Provider Signature

05/30/2024

Date

Clint Rux

Inspector Signature

05/30/2024

Date