

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Doland Community Daycare**

City: **Doland**

Provider Number: **011102464**

Inspector: **Eric Janke**

Date of Inspection: **03/22/2023**

Time of Inspection: **3:48 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

12. Are exits and exit corridors maintained in a safe manner? 61:15:05:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

Corrections To Be Made:

**The exit in basement was blocked upon arrival.**

**The exits and exit corridors cannot be obstructed.**

**Correction: The exit in the basement was unblocked immediately during the inspection.**

Agency Action:

### Compliance Plan

Suggested  
Completion  
Date:

**03/22/2023**

Actual  
Completion  
Date:

**03/22/2023**

Status: **Corrected Immediately**

**Melinda Rowe**

Provider Signature

**03/22/2023**

Date

**Eric Janke**

Inspector Signature

**03/22/2023**

Date