

**Facility Safety Inspection
Fire & Life Safety / Environmental Health
Before & After School Center - School Location
Compliance Plan**

Provider's Name: **Saint Lawrence School OST**

City: **Milbank**

Provider Number: **011102548**

Inspector: **Eric Anderson**

Date of Inspection: **08/10/2022**

Time of Inspection: **2:07 PM**

Provider was found to be in full compliance

Brenda Anderson

Provider Signature

08/10/2022

Date

Eric Anderson

Inspector Signature

08/10/2022

Date