

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **LOLA - Center**

City: **Mobridge**

Provider Number: **011102577**

Inspector: **Clint Rux**

Date of Inspection: **06/13/2024**

Time of Inspection: **2:30 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

Corrections To Be Made:

The West exit has items stored in front of the door that did not allow for its use in the event of an emergency.

The West exit needs corridor needs have items removed that are obstructing the exit.

Correction: The items in the West exit have been removed from obstructing the exit.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

06/20/2024

Status: **Corrected**

Actual
Completion
Date:

07/22/2024

Emily Moser

Provider Signature

06/13/2024

Date

Clint Rux

Inspector Signature

06/13/2024

Date