

Facility Safety Inspection Fire & Life Safety / Environmental Health Before & After School Center - School Location Compliance Plan

Provider's Name: **Great After School Place - Hillcrest Location**

City: **Brookings**

Provider Number: **011512104**

Inspector: **Charles Schmidt**

Date of Inspection: **04/24/2023**

Time of Inspection: **4:50 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

23. Is the inside and outside of the facility free of other hazardous conditions? 67:42:11:15

<p>Corrections To Be Made:</p> <p>Ensure proper egress is maintained from gymnasium. Current egress restricted due to newly started construction.</p> <p>Correction: Pictures received showing there is a proper exit from the gym that is not restricted.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">04/30/2023</td> <td style="text-align: center;">04/26/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	04/30/2023	04/26/2023
Suggested Completion Date:	Actual Completion Date:				
04/30/2023	04/26/2023				

Abby Kwasniewski

Provider Signature

04/24/2023

Date

Charles Schmidt

Inspector Signature

04/24/2023

Date