

# Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Hamlin Community Daycare**

City: **Hayti**

Provider Number: **011515290**

Inspector: **Charles Schmidt**

Date of Inspection: **02/07/2023**

Time of Inspection: **11:16 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## A. FIRE AND LIFE SAFETY

8. Are exits and exit corridors maintained in a safe manner? 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths of 36 inches; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p><b>North exit locked at time of inspection. Not fitted with single action hardware.</b></p> <p><b>Correction: Verifictaion received that this is not an exit that is used as a primary exit, however, hardware has been replaced.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>03/07/2023</b></td> <td style="text-align: center;"><b>03/07/2023</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>03/07/2023</b>	<b>03/07/2023</b>
Suggested Completion Date:	Actual Completion Date:				
<b>03/07/2023</b>	<b>03/07/2023</b>				

**Amy Fuller**

Provider Signature

**02/07/2023**

Date

**Charles Schmidt**

Inspector Signature

**02/07/2023**

Date