

Family Day Care Inspection Compliance Plan

Provider's Name: **Barbara Mears**

City: **Sioux Falls**

Provider Number: **011515352**

Inspector: **Sarah Boese**

Date of Inspection: **11/07/2023**

Time of Inspection: **10:12 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

C. Health and Safety Features of the Home- Indoor Environmental Observations

76. Are all open-sided floor and wall openings, and platforms inside & outside the home which are more than 30 inches above ground level, guarded by a barrier that is at least 36 " tall and no more than 5 " between openings? 67:42:17:38

Corrections To Be Made:

The play equipment is installed according to manufacturers instructions but there are areas in the upper level that are more than 30 inches above ground level that are not guarded by a barrier.

All open sided floor and wall openings, and platforms inside and outside the home which are more than 30 inches above ground level shall be guarded by a barrier with no more than 5 inches between openings.

The provider installed barriers over the open sided wall openings.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

11/24/2023

Actual
Completion
Date:

11/20/2023

Status: **Corrected**

Barbara Mears

Provider Signature

11/07/2023

Date

Sarah Boese

Inspector Signature

11/07/2023

Date