

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Sioux Falls Lutheran Eagle Care**

City: **Sioux Falls**

Provider Number: **011515428**

Inspector: **Todd Lowe**

Date of Inspection: **08/06/2024**

Time of Inspection: **1:06 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

There was not a carbon monoxide detector installed.

A carbon monoxide detector must be installed, according to the manufacturer's instructions, if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.

Correction: The program installed a carbon monoxide detector.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

08/16/2024

Actual
Completion
Date:

08/08/2024

Status: **Corrected**

Brenda Bernard

Provider Signature

08/06/2024

Date

Todd Lowe

Inspector Signature

08/06/2024

Date