

# Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **SDSU Laboratory Preschool**

City: **Brookings**

Provider Number: **011515520**

Inspector: **Charles Schmidt**

Date of Inspection: **09/10/2024**

Time of Inspection: **2:25 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## B. Environmental Health

58. Is the playground equipment installed according to the manufacturer ' s instructions and in good repair? 67:42:17:35

<p>Corrections To Be Made:</p> <p><b>Handrail needs repair on purple storage shed.</b></p> <p><b>Playground equipment must be in good repair.</b></p> <p><b>Correction: Verification received that handrail has been repaired.</b></p>	<p>Agency Action:</p> <p><b>Compliance Plan</b></p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;"><b>10/10/2024</b></td> <td style="text-align: center;"><b>09/25/2024</b></td> </tr> </table> <p>Status: <b>Corrected</b></p>	Suggested Completion Date:	Actual Completion Date:	<b>10/10/2024</b>	<b>09/25/2024</b>
Suggested Completion Date:	Actual Completion Date:				
<b>10/10/2024</b>	<b>09/25/2024</b>				

**Jennifer Johnson**

Provider Signature

**09/10/2024**

Date

**Charles Schmidt**

Inspector Signature

**09/10/2024**

Date