

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **SDSU Early Learning Center** City: **Brookings** Provider Number: **011517222**
 Inspector: **Charles Schmidt** Date of Inspection: **04/15/2024** Time of Inspection: **11:38 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

18. Are exits and exit corridors maintained in a safe manner? 61:15:05:05; 61:15:06:05 NOTE: Exits can't pass through storeroom, bathroom, kitchen; corridor & aisle widths maintained at 36 inches or more; exits cannot be obstructed.

<p>Corrections To Be Made:</p> <p>A door in a classroom that is used as an exit has a childproof device on the doorknob that is not approved by licensing.</p> <p>Exits cannot be obstructed.</p> <p>Correction: The childproof device was removed from doorknob at time of inspection; the provider will ensure the exits are always unobstructed.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">04/22/2024</td> <td style="text-align: center;">04/22/2024</td> </tr> </table> <p>Status: Corrected Immediately</p>	Suggested Completion Date:	Actual Completion Date:	04/22/2024	04/22/2024
Suggested Completion Date:	Actual Completion Date:				
04/22/2024	04/22/2024				

Barb Caulfield

Provider Signature

04/15/2024

Date

Charles Schmidt

Inspector Signature

04/15/2024

Date