

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **DASH**

City: **Toronto**

Provider Number: **011517579**

Inspector: **Charles Schmidt**

Date of Inspection: **11/16/2023**

Time of Inspection: **2:08 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

Building did not have a carbon monoxide detector at time of inspection.

Correction: Verification received that program has a carbon monoxide detector installed.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

12/16/2023

Actual
Completion
Date:

12/19/2023

Status: **Corrected**

Jeannette

Provider Signature

11/16/2023

Date

Charles Schmidt

Inspector Signature

11/16/2023

Date