

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Hanson CO CLC-Alexandria
School**

City: **Alexandria**

Provider Number: **014510700**

Inspector: **Todd Lowe**

Date of Inspection: **10/02/2024**

Time of Inspection: **1:19 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

Currently there is no carbon monoxide detection within the school.

Received verification that carbon monoxide detectors had been installed.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

10/10/2024

Actual
Completion
Date:

10/18/2024

Status: **Corrected**

Ann Bartscher

Provider Signature

10/02/2024

Date

Todd Lowe

Inspector Signature

10/02/2024

Date