

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **Crayon Box II**

City: **Salem**

Provider Number: **014511967**

Inspector: **Todd Lowe**

Date of Inspection: **09/28/2023**

Time of Inspection: **11:53 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. Fire and Life Safety

23. Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane, natural, gas, etc.? 61:15:01:01

Corrections To Be Made:

There are no carbon monoxide detectors in the buidling.

A carbon monoxide detector was installed.

Agency Action:

Compliance Plan

Suggested
Completion
Date:

10/05/2023

Actual
Completion
Date:

10/04/2023

Status: **Corrected**

Rhonda Mead

Provider Signature

09/28/2023

Date

Todd Lowe

Inspector Signature

09/28/2023

Date