

Facility Safety Fire & Life Safety / Environmental Health Compliance Plan

Provider's Name: **James Valley Christian School** City: **Huron** Provider Number: **014512049**
 Inspector: **Neal Cruse** Date of Inspection: **08/08/2023** Time of Inspection: **9:53 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. Environmental Health

59. For a center program, is the outdoor play area enclosed with a fence that is at least 48 " high?
67:42:17:35

<p>Corrections To Be Made:</p> <p>Fence at least 48" high must be installed around outdoor play area.</p> <p>Center programs must have an enclosed outdoor play area with a fence at least 48" high.</p> <p>The program provided verification that their outdoor play area is enclosed with a fence that is 48" high.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">09/05/2023</td> <td style="text-align: center;">09/08/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	09/05/2023	09/08/2023
Suggested Completion Date:	Actual Completion Date:				
09/05/2023	09/08/2023				

Jeremy Zajicek

Provider Signature

08/08/2023

Date

Neal Cruse

Inspector Signature

08/08/2023

Date