

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Stickney Community Daycare** City: **Stickney** Provider Number: **014512569**
 Inspector: **Carrie Lewis** Date of Inspection: **03/27/2023** Time of Inspection: **8:37 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

59. Is playground equipment properly installed and maintained in good repair? Are sandboxes free from animal excrement and do they permit drainage? 67:42:11:02

<p>Corrections To Be Made:</p> <p>The north swing on the outdoor play equipment had numerous cracks on it.</p> <p>Playground equipment will be properly installed and maintained in good repair.</p> <p>Verification of new swings having been installed was received.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">04/10/2023</td> <td style="text-align: center;">05/08/2023</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	04/10/2023	05/08/2023
Suggested Completion Date:	Actual Completion Date:				
04/10/2023	05/08/2023				

Alysha Gray

 Provider Signature

03/27/2023

 Date

Carrie Lewis

 Inspector Signature

03/27/2023

 Date